



MAKER WEB

**CNC SOFTWARE CERTIFICATION
VCARVE PRO**

VCarve
PRO

CNC TUTORIAL DESCRIPTION

A CNC Milling machine is a computer controlled machine that can be used to make very precise 3D parts. The machine works by cutting or removing material from the stock material with a rotating cutting tool. The machine does this by guiding the tool in all three directions of the cartesian coordinate system, that meaning along the X, Y and Z axis. This tutorial will certify you to create and submit files for the CNC Machine. Before proceeding with this tutorial you must visit the CNC Lab website and review the CNC Basics PDF.


TABLE OF CONTENTS

- Part 1:** Startup and Interface
- Part 2:** Skills and Learning Objectives
- Part 3:** Parameters and Cutting Area
- Part 4:** VCarve Startup Material Settings
- Part 5:** Importing Geometry
- Part 6:** Viewing, Modifying and Moving Geometry
- Part 7:** Creating Roughing Toolpath
- Part 8:** Creating Finishing Toolpath
- Part 9:** Creating Pocketing Toolpath
- Part 10:** Creating Profiling Toolpath
- Part 11:** Creating Job Sheet
- Part 12:** Exporting Toolpaths
- Part 13:** Visiting the CNC Lab


SUPPLEMENTAL RESOURCES

<https://www.vectric.com/support/tutorials/vcarve-pro>

Part 1: Startup and Interface




In order for the CNC machine to work it needs coded instructions to tell it what to do. While a design is made in CAD (computer Aided Drafting) software, “toolpaths” and the resulting code is generated in CAM (Computer Aided Machining) software. There are many CAM software packages available but at Union we use a software called VCarve Pro. This software uses a 2D or 3D design and allows the user to create various toolpaths which can be exported as code files for the CNC machine.




VCarve Pro can create 2D toolpaths to cut out material and can also create 3D tool paths to sculpt complex 3D objects. This CNC certification tutorial is intended to introduce you to the basic steps to create toolpath operations which will be checked and run by CNC operators in the CNC Lab. The software is installed on a computer in the Digital Arts Lab in the Visual Arts Building. Please visit the Laser Cutting Lab during our open hours to use VCarve Pro.

Part 2: Skills and Learning Objectives




This tutorial will enable you to create 4 toolpath operations that can be exported and subsequently cut on the CNC machine by one of the operators. The CNC Lab supplies all the bits and materials for the certification tutorial. Once your file is cut correctly you will be placed on the certified list and can subsequently create files, schedule cut times and make use of the CNC machine. **Please note that only Maker Web employees and specifically trained faculty and students will OPERATE the CNC Machine. This tutorial DOES NOT cover operation of the machine.**



As part of the tutorial you will create the following operations: 1) Horizontal Roughing 2) Parallel Finishing 3) Pocketing 4) Profiling. VCarve offers several other toolpath types and within each toolpath type there are many options. However, these 4 are the most common and will enable you to create a variety of work on the CNC in the future.

Part 3: Parameters and Cutting Area



The template file includes a 3D surface and 2D lines for various inputs. The CNC Lab provides the template file, bits and an 8" x 8" square pieces of MDF, plywood and foam for the tutorial. All you need to do is create all the appropriate files and bring them to the Lab during our open hours.

Things to note:

1. The actual allowable cutting area for the CNC machine is 48"x 96" x 6". These are maximum dimensions but the machine is only capable of cutting certain geometry. Too steep of a cut and too short of a bit can result in conflicts. The example shows how a cut depth of three inches can be both good and bad depending on the specific geometry
2. The machine cannot do undercuts. See example below.

GOOD CUT: Shows a cross-section of a bit cutting a smooth curve to a depth of 3".


BAD CUT: Shows a cross-section of a bit cutting a sharp corner to a depth of 3", with a red circle highlighting the area where the bit cannot reach.

GOOD CUT: Shows a 3D surface plot of a smooth wavy surface.


BAD CUT: Shows a 3D surface plot of a wavy surface with a sharp undercut.

Before getting started there are some important things to note about the CNC machine and the geometry it can and can not cut. Take note of undercuts and overall cut depth compared to bit length.

Part 4: VCarve Startup Material Settings




Start VCarve and Create a new file.




The home screen has some material options. Most of the defaults are correct but you will have to fill in the material size in millimeters. For this tutorial we will be using a 8" x 8" x 3/4" piece of sheet material. In millimeters this comes to 203.2mm x 203.2mm x 19.05mm. Input these values and make sure the Z=0 position is set to Machine Bed and the resolution is set to Very High. Click OK.

Part 5: Importing Geometry




This is the VCarve user interface. From here you can import or create geometry, create and edit and preview toolpaths and finally export them. For this tutorial you will want to import the accompanying template file. It is an STL file.




Click New > Import > Component/3D Model. Navigate to where you have the template files located and select the “surface” file and import it.

Part 6: Viewing, Modifying and Moving Geometry




Once you have selected and imported the file there will be some options about position and scale. All of the defaults can stay the same except the Zero Plane. This has to match the zeroing strategy defined by the material description. Make sure the zero plane is **ALWAYS** set to the lowest it can be or the bottom of the material. In this case it's set to 19.05mm.




Once you click okay, you will see a 3D Preview of you model. It should be in the appropriate XYZ position but if necessary it can be moved by clicking on the 2D View Tab. To navigate around the model use the mouse. The **Left** mouse button rotates the model. The **Right** mouse button zooms in and out and the **Middle** mouse button pans around the model.

Part 6: Viewing, Modifying and Moving Geometry




If you click on the surface it selects it. Click the surface again to show the grips. Moving these grips can move, rotate and scale the surface. We don't want to modify the surface at all in this tutorial but it is important to know.




Next we want to import the vector lines that will define various boundaries for milling. Click File > Import > Vectors. Navigate to where you have the template files located and select the "boundaries" file and import it.

Part 6: Viewing, Modifying and Moving Geometry




You should see the outlines in purple. Click off them to deselect them. They should now be black.




Now that we have all the geometry files imported we want to go back to the 3D View and start making tool paths. Click on the 3D View button then the Toolpaths Button on the upper right. This will open the toolpath dialog window.

Part 7: Creating Roughing Toolpath




It is important to sequence your toolpaths correctly. For this tutorial we want to carve the surface then cut the pocket and finally cut the piece out. In order to carve the smooth surface we need to cut deeply into the material and also use a small bit. Because that will exceed the recommended cut depth we must first rough out the surface in steps and then finish it with a different operation. To do this we will first choose “3D Roughing Toolpath”.




This opens the toolpath dialog box where you can modify all the settings for the cut. Most of the default setting are fine but we do need to select the bit and set the appropriate parameters. Click on the Select Bit button which will open the dialog box.

Part 7: Creating Roughing Toolpath

NOTE: The values given are for this tutorial only and will be different for different bits and materials. Always refer to the Feeds and Speeds Guide for speeds and note that the cut depth should equal the diameter of the bit and that the stepover should be in the range of 20-50% depending on desired finish.




First, select the 1/2" Ball Nose. The default values may not be correct so be sure to check EACH of the parameters. First make sure the **Diameter** is set to .5". Next make sure the **Number of Flutes** is set to 2. Make sure the **Pass Depth** and **Stepover** are set to .25". Finally set the Spindle Speed to 10,000 rpm, the Feed Rate is set to 180 inches/minute and the Plunge Rate is set to 30. Click Apply and then Select. For more information on these values please refer to the CNC Basics PDF.




Once you have set all of the parameters and clicked Select. The dialog box will disappear and you are ready to process the toolpath. Click "Calculate". The software will do some processing and show you a preview of the toolpath and give you a chance to simulate the movement of the bit.

Part 7: Creating Roughing Toolpath




Once you see the toolpaths you can click on the Play button to the right to begin the simulation. To view it again you can click the Reset Preview and Play again.




Inspect the preview of the cut to be sure everything looks okay. If everything looks appropriate click on the Close button to finalize the toolpath.

Part 8: Creating Finishing Toolpath




This will bring you back to the root toolpath dialog box. You will now see your first toolpath operation has been created at the bottom of the dialog box. Note that you can edit this toolpath by double clicking on it which opens up the previous parameters dialog box. Next we want to create our next toolpath, 3D Finishing. Click the 3D Finishing button.




The cut parameters dialog window should look familiar as it is similar to the dialog box for each operation because they each have some similar parameters. Like before we want to leave most of the default settings as they are but we need to change the Boundary Offset to 3mm. Also we need to select and modify the Bit and it's cutting parameters. While we used a 1/2" ball mill for roughing, we will use a 1/4" flat end mill for the finishing operation. Click the Bit Selection button.

Part 8: Creating Finishing Toolpath

NOTE: The values given are for this tutorial only and will be different for different bits and materials. Always refer to the Feeds and Speeds Guide for speeds and note that the cut depth should equal the diameter of the bit and that the stepover should be in the range of 20-50% depending on desired finish.




Select the 1/4" End Mill to open the its parameters. These should look familiar to you. There are some differences though and like before it is important to review each setting. make sure the **Diameter** is set to .25". Next make sure the **Number of Flutes** is set to 2. Make sure the **Pass Depth** is set to .25" and the **Stepover** are set to **25%**. Finally set the Spindle Speed to 10,000 rpm, the Feed Rate is set to 180 inches/minute and the Plunge Rate is set to 30. Click Apply and then Select. For more information on these values please refer to the CNC Basics PDF.




Once you have set all of the parameters and clicked Select, the dialog box will disappear and you are ready to process the toolpath. Click "Calculate". The software will do some processing and show you a preview of the toolpath and give you a chance to simulate the movement of the bit.

Part 8: Creating Finishing Toolpath




Once you see the toolpaths you can click on the Play button to the right to begin the simulation. To view it again you can click the Reset Preview and Play again. You will also see your new toolpath added to the list at the bottom. Click Play to watch the simulation.




Inspect the preview of the cut to be sure everything looks okay. If everything looks appropriate click on the Close button to finalize the toolpath.

Part 9: Creating Pocketing Toolpath




This will bring you back to the root toolpath dialog box. You will now see your list of toolpath operations at the bottom of the dialog box. Note that you can edit these toolpaths by double clicking on them. Next we want to create our next toolpath, Pocketing. Click the Pocketing Button.




The cut parameters dialog window should look familiar. Because a Pocketing operation requires a boundary we will switch to a 2D view and select the inner vector line as the boundary. It should turn purple. Like before we want to leave most of the default settings as they are but we need to change the Cut Depth parameters. Set the Start Depth to 0 and the Cut Depth to 15mm. Also we need to select and modify the Bit and it's cutting parameters. Click the Bit Selection button.

Part 9: Creating Pocketing Toolpath

NOTE: The values given are for this tutorial only and will be different for different bits and materials. Always refer to the Feeds and Speeds Guide for speeds and note that the cut depth should equal the diameter of the bit and that the stepover should be in the range of 20-50% depending on desired finish.




For the Pocketing Operation we will be using the same bit as the Finishing Operation, the 1/4" End Mill. It should retain its settings from before but review to be sure. Make sure the **Diameter** is set to .25". Next make sure the **Number of Flutes** is set to 2. Make sure the **Pass Depth** is set to .25" and the **Stepover** are set to **25%**. Finally set the Spindle Speed to 10,000 rpm, the Feed Rate is set to 180 inches/minute and the Plunge Rate is set to 30. Click Apply and then Select.




Once you have set all of the parameters and clicked Select, the dialog box will disappear and you are ready to process the toolpath. Click "Calculate". The software will do some processing and show you a preview of the toolpath and give you a chance to simulate the movement of the bit. For better viewing you can switch back to the 3D View.

Part 9: Creating Pocketing Toolpath




Once you see the toolpaths you can click on the Preview all Toolpaths button to the right to begin the simulation of each sequential toolpath. To view it again you can click the Reset Preview and Play again. You will also see your new toolpath added to the list at the bottom.




Inspect the preview of the cut to be sure everything looks okay. If everything looks appropriate click on the Close button to finalize the toolpath.

Part 10: Creating Profiling Toolpath




This will bring you back to the root toolpath dialog box. You will now see your list of toolpath operations at the bottom of the dialog box. Next we want to create our final toolpath, Profiling. Click the Profiling Button.




A Profiling operation also requires a boundary so we will switch to a 2D view and select the outer vector line as the boundary. It should turn purple. First, we need to change the Cut Depth parameters. Set the Start Depth to 0 and the Cut Depth to 20mm. We also want to set the cut to be Outside/Right of the vector line. Finally we need to select and modify the Bit and it's cutting parameters. Click the Bit Selection button.

Part 10: Creating Profiling Toolpath

NOTE: The values given are for this tutorial only and will be different for different bits and materials. Always refer to the Feeds and Speeds Guide for speeds and note that the cut depth should equal the diameter of the bit and that the stepover should be in the range of 20-50% depending on desired finish.




For the Profiling Operation we will be using the same bit as the Finishing Operation, the 1/4" End Mill. It should retain its settings from before but review to be sure. Make sure the **Diameter** is set to .25". Next make sure the **Number of Flutes** is set to 2. Make sure the **Pass Depth** is set to .25" and the **Stepover** are set to **25%**. Finally set the Spindle Speed to 10,000 rpm, the Feed Rate is set to 180 inches/minute and the Plunge Rate is set to 30. Click Apply and then Select.




Once you have set all of the parameters and clicked Select, the dialog box will disappear and you are ready to process the toolpath. Click "Calculate". The software will warn you that you are cutting through the material. Since your Profiling toolpath is set to cut to 20mm. It is .95mm deeper than the material to be sure it's a clean cut. Click okay. Next you should see a preview of the toolpath and have a chance to simulate the movement of the bit. For better viewing you can switch back to the 3D View.

Part 10: Creating Profiling Toolpath




Once you see the toolpaths you can click on the Preview all Toolpaths button to the right to begin the simulation of each sequential toolpath. To view it again you can click the Reset Preview and Play again. You will also see your new toolpath added to the list at the bottom.




Inspect the preview of the cut to be sure everything looks okay. If everything looks appropriate click on the Close button to finalize the toolpath.

Part 11: Creating Job Sheet




This will bring you back to the root toolpath dialog box. You will now see your list of toolpath operations at the bottom of the dialog box. Next we need to create a Job Sheet which describes all of the cutting operations. Click the button and save the HTML file in a location you can find. This file must be opened in a browser window, saved as a PDF and brought to the CNC Lab with your other files.




Simply double click the HTML file to open it in a browser window and then print as a PDF.

Part 12: Exporting Toolpaths



Your Job Sheet should be a multipage page document similar to what you see above. Note all of the valuable information including cut times, cut parameters, bits used and stock material size.



Finally we want to export each of the toolpaths individually. Highlight each of the tool paths individually and click the Save Toolpath button. When you save the files it's very important to be sure you have the correct post processor. On the pulldown menu be sure to choose **Laguna Swift CNC (mm) (*.mmg)**. Save the files folder you can locate. You should end up with 4 .mmg files. Be sure to name them as follows: Your initials_cut number_cut type (for example CB_1_RT, CB_2_FT, CB_3_PoT, CB_4_PrT).

Part 13: Visiting the CNC Lab

Please note you must be present for the duration of your cut. It should take about 30 minutes and it is an important part of the process to be sure there are no issues with the cuts



You are now ready to have your files cut in the CNC Lab. Please visit the CNC Lab Website and submit your files (1-“Cutting Checklist” 2-Your VCarve Pro file (.CRV), 3-Your Job Sheet (.PDF), and 4- Your cut Files x4 (.MMG). We will contact you to schedule a time for the cut. Please do not visit the Lab without a scheduled appointment.

NOTE: You are responsible for providing materials for all your projects after the certification tutorial. The Lab provides materials for the tutorial ONLY.

NOTE: The CNC Lab provides a limited number of bits to students but it's best to check with us to verify bit availability before making subsequent toolpaths after the tutorial.

NOTE: For every future cut you want to make on the CNC you must submit it through our website. You will need to upload a completed “Cutting Checklist”, Your VCarve Pro file (.CRV), Your Job Sheet (.PDF), and your Cut Files x4 (.MMG).

Once your file is cut correctly you will be placed on the certified list and can subsequently create files, and have them cut on the CNC machine. **Please note that only Maker Web employees and specifically trained faculty and students will OPERATE the CNC Machine. This tutorial DOES NOT cover operation of the machine.**